

TABLE OF CONTENTS

1.0 BACKGROUND.....	1
1.1 Introduction	1
1.2 Project Purpose and Goals.....	1
1.3 Taylor River and its Watershed.....	2
1.4 Existing Structures.....	3
1.4.1 I-95 Bridge	4
1.4.2 Primary Spillway and Associated Structures	4
1.4.3 Dam and Fishway Maintenance	6
1.4.4 Flooding and Tides	6
2.0 ALTERNATIVES	8
2.1 Introduction	8
2.2 Alternative A: No Action.....	8
2.3 Alternative B: Replacement of I-95 Bridge and New Spillway/Fishway	9
2.3.1 Proposed Bridge	9
2.3.2 Proposed Spillway	9
2.3.3 Proposed Fishway	10
2.3.3.1 Alternative B1: Denil Fishway	10
2.3.3.2 Alternative B2: Alaskan Steep Pass Fishway	11
2.3.3.3 Alternative B3: Rock Ramp Fishway.....	11
2.4 Alternative C: I-95 Bridge Replacement without Spillway.....	11
3.0 ENVIRONMENTAL ASSESSMENT OF ALTERNATIVES.....	12
3.1 Hydraulic Analysis	12
3.1.1 HydroCAD® Model Development.....	12
3.1.2 HEC-RAS Model Development	13
3.1.3 Abutter Flood Conditions.....	14
3.2 Geology	14
3.2.1 Bedrock Geology	14
3.2.2 Surficial Geology.....	15
3.2.3 Soils.....	15
3.2.4 NHDOT Geotechnical Information.....	15



3.3	Sediments	17
3.3.1	Physical Characteristics of Sediments	18
3.3.1.1	Methodology.....	18
3.3.1.2	Results	18
3.3.1.2.1	<i>Taylor River Pond</i>	18
3.3.1.2.2	<i>Rice Dam Impoundment</i>	19
3.3.2	Chemical Characteristics of Sediments.....	20
3.3.2.1	Methodology.....	20
3.3.2.1.1	<i>Sediment Chemistry</i>	20
3.3.2.1.2	<i>Sediment Toxicity Bioassays</i>	21
3.3.2.2	Results Chemical Characteristics	22
3.3.3	Fish Tissue Analyses	22
3.3.3.1	Field Sampling.....	23
3.3.3.2	Laboratory Analysis.....	24
3.3.3.3	Results Fish Tissue and Human Health Assessment.....	24
3.3.4	Ecological Risk Assessment	26
3.3.5	Impact Analysis.....	26
3.3.5.1	Alternative A.....	27
3.3.5.2	Alternative B.....	27
3.3.5.3	Alternative C.....	28
3.4	Groundwater Resources and Wells	29
3.4.1	Existing Hydrogeologic Conditions	29
3.4.2	Water Supply Well Data	29
3.4.3	Impact Analysis.....	31
3.4.3.1	Alternative A.....	31
3.4.3.2	Alternative B.....	31
3.4.3.3	Alternative C.....	31
3.5	Infrastructure	32
3.6	Fire Fighting Water Supply	32
3.6.1	Existing Conditions	32
3.6.2	Impact Analysis.....	32
3.6.2.1	Alternative A.....	32
3.6.2.2	Alternative B.....	33
3.6.2.3	Alternative C.....	33



3.7	Socio-Economic Issues	33
3.7.1	Public Involvement.....	33
3.7.2	Open Space.....	33
3.7.3	Impact Analysis.....	34
3.7.3.1	Alternative A.....	34
3.7.3.2	Alternative B.....	34
3.7.3.3	Alternative C.....	34
3.8	Recreational Use.....	35
3.8.1	Existing Conditions	35
3.8.2	Impact Analysis.....	35
3.8.2.1	Alternative A.....	35
3.8.2.2	Alternative B.....	36
3.8.2.3	Alternative C.....	36
3.9	Water Quality.....	36
3.9.1	Existing Conditions	36
3.9.2	Impact Analysis.....	37
3.9.2.1	Alternative A.....	37
3.9.2.2	Alternative B.....	38
3.9.2.3	Alternative C.....	38
3.10	Fisheries.....	38
3.10.1	Existing Conditions	38
3.10.1.1	Recent Diadromous Fisheries Information:.....	38
3.10.1.2	Fish Passage and Potential Upstream Anadromous Fish Habitat.....	39
3.10.1.3	Existing Habitat Conditions and Resident Fishery:	40
3.10.2	Impact Analysis:.....	42
3.10.2.1	Alternative A.....	42
3.10.2.2	Alternative B.....	42
3.10.2.3	Alternative C.....	43
3.11	Listed Species of Concern.....	44
3.11.1	Existing Conditions	44
3.11.2	Impact Analysis.....	44
3.11.2.1	Alternative A.....	44
3.11.2.2	Alternative B.....	44
3.11.2.3	Alternative C.....	44



3.12	Wetlands	45
3.12.1	Existing Conditions	45
3.12.2	Impact Analysis.....	46
3.12.2.1	Alternative A.....	46
3.12.2.2	Alternative B.....	46
3.12.2.3	Alternative C.....	46
3.13	Cultural and Historic Resources	48
3.13.1	Area of Potential Effect	48
3.13.2	Existing Conditions	48
3.13.3	Archaeological Potential.....	49
3.13.4	Impact Analysis.....	49
3.13.4.1	Alternative A.....	49
3.13.4.2	Alternative B.....	49
3.13.4.3	Alternative C.....	50
4.0	SUMMARY	51
5.0	CONCEPTUAL CONSTRUCTION COST ESTIMATES	53
REFERENCES		55

TABLES

- 1 - Existing Taylor River Pond Dam -HydroCAD® Analysis Summary, Alternative A – No Action
- 2 - Taylor River Pond Dam - HEC-RAS Analysis Summary; Alternative B: New 70-Foot Bridge WITH Spillway
- 3 - Taylor River Pond Dam - HEC-RAS Analysis Summary, Alternative C: New 70-Foot Bridge WITHOUT Spillway
- 4 - Taylor River Pond Dam – HEC-RAS Analysis Summary, Alternatives B and C
- 5 - Taylor River Pond Dam Impoundment – Sediment Quality – Station Locations (Upstream and Downstream
- 6 - Taylor River Pond Dam Impoundment – Sediment Quality – Grain Size
- 7 - Taylor River Pond Dam Impoundment - Sediment Accumulation – Measured on December 18, 2006
- 8 - Taylor River Pond Dam Impoundment – Sediment Quality – All Compounds (Except VOCs)
- 9 - Taylor River Pond Dam Impoundment – Sediment Quality – Hazard Quotient
- 10 - Taylor River Pond Dam Impoundment – Sediment Quality – Volatile Organic Compounds



- 11 - Taylor River – Fish Sampling in Spring 2007
- 12 - Organic Compounds in Fish Tissues in Taylor River Impoundment – Summary of Laboratory Reports (ug/kg)
- 13 - Taylor River – Fish Tissue Pesticide Concentrations, as used for Human Health Assessment (ug/kg)
- 14 - Taylor River – Summary Statistics for Contaminants in Fish Fillets
- 15 - Taylor River –Summary of Data and Ecological Risk
- 16 - Taylor River Pond Dam Impoundment – Temperature/DO Profile, Recorded on Taylor River Pond, August 31, 2006
- 17 - Trophic levels (after Vollenweider and Kerekes, 1982), and range of values for Taylor River Pond
- 18 - Taylor River – Numbers of River Herring Returning to Fishways on Coastal New Hampshire Rivers from 1972 – 2005
- 19 - Results of Fish Sampling by NH Fish and Game Department in Taylor River Pond, April through June, 2007
- 20 - Table 20 – Summary of Impacts (*within Text*)
- 21 - Table 21 – Conceptual Construction Cost Estimates (*within Text*)

FIGURES

- 1 - Site Vicinity Map
- 2 - Taylor River Dam Watershed Area
- 3 – 6 Hydraulic Model Cross Sections
- 7 - Taylor River Tides at Hampton Harbor, NH
- 8 - Proposed Bridge / Spillway & Fishway Schematic
- 9 - Alternative A – Existing Bridge and Spillways – No Action
- 10 - Alt. B – New Bridge, Spillway and Fishway with Normal Flow and Ebb Tide
- 11 - Alt. B – New Bridge, Spillway and Fishway, 100-year Storm (U/S) with Highest Monthly Tide (D/S)
- 12 - Alt. C – New Bridge without Spillway, Normal Flow at Ebb Tide
- 13 - Taylor River Pond Dam Impoundment – Sediment Sampling Stations
- 13A - Sediment Accumulation in Taylor River Pond Dam Impoundment
- 14 -16 Thickness of Accumulated Sediment, Taylor River Pond, 10-23-07
- 17 - Upper Taylor River Pond Dam Impoundment, Stations TR-S1 (chemistry) and TR-S8 (grain size only)
- 18 - Sediment Sampling Station TR-S1 Location (View 1)
- 19 - Sediment Sampling Station TR-S1 Location (View 2)
- 20 - Mid-Section of the Taylor River Pond Dam Impoundment – TR-S2 and TR-S7 Sediment Sampling Sub-Sample Locations



- 21 - Sediment Sample Taken from TR-S2 (Sub-Sample 3 of 3)
- 22 - Lower Taylor River Pond Dam Impoundment – Sediment Sampling Location TR-S5 and TR-S6
- 23 - Sediment Sample Taken from Station TR-S5 (Sub-Sample 1 of 2)
- 24 - Sediment Core at Station TR-S5
- 25 - Sediment Sampling Station TR-S4 and Sub-Sampling Locations
- 26 - Sediment Sampling Station TR-S4 (Sub-Sample 2 of 3) [View 1 – Looking to the west.]
- 27 - Sediment Sampling Station TR-S4 (Sub-Sample 2 of 3) [View 2 – Looking to the east.]
- 28 - Rice Dam Impoundment and Sediment Sampling Station TR-S11 Location
- 29 - Gill net and electrofishing boat fish sampling areas for public and wildlife risk assessment sampling in the Taylor River Pond in 2007, Hampton-Hampton Falls, NH
- 30 - Types of Recreational Uses within the Taylor River Pond and Number of Respondents
- 31 - Dissolved Oxygen Concentration Statistics for the Taylor River, August 31 – September 5, 2006, NHDES VRAP
- 32 - Vertical dissolved oxygen concentrations profiles at Station W-06
- 33 - Taylor River Pond – Continuous dissolved oxygen concentrations and temperature at Station W-06
- 34 - Taylor River – Salinity (September 26 to November 2, 2006)
- 35 - Taylor River – Water Elevation (feet) (September 26 to November 2, 2006)
- 36 - Salinity downstream of Taylor River Dam
- 37 - Wetland Classification Map
- 38 - Area of Potential Effect for Cultural Resources

APPENDICES

- Appendix A. Bathymetric Survey Data [“Bathymetric Survey and Sediment Probing for the Taylor River Dam/Bridge Project, Hampton, NH”, dated December 27, 2006, by HYDROTERRA Environmental Services, LLC.]
- Appendix B. NHDES Dam Safety Bureau Documents
- Appendix C. Geotechnical Information - “Input to Feasibility Study”, dated October 23, 2007, by GEI Consultants, Inc.
- Appendix D. “Sediment Management Plan”, dated June 2009, by The Louis Berger Group, Inc.
- Appendix E. “Information on Existing Water Wells in the Vicinity of Taylor River Pond...”, by GEI Consultants, Inc., dated July 6, 2009.



Appendix F. NHDOT memo from James T. Minichiello, Staff Appraiser, to Harry C. Hadaway, Jr., Chief ROW Appraiser, entitled "Appraisal Consulting Assignment, Real Property Value Loss Estimate.....", dated May 20, 2009.

Appendix G. Recreational Survey Data

Appendix H. Correspondence

ADDITIONAL DATA CD

Folder 1: HydroCAD® Hydraulic Model Results
HEC-RAS Hydraulic Model Results

Folder 2: Sediment Quality, Laboratory Analysis Reports: Toxicological Evaluation, SVOCs, Pesticides, PCBs, Total Metals and TOC
Sediment - Grain Size Distribution Analysis Report

Folder 3: Fish Tissue Laboratory Analysis Reports

Folder 4: Dissolved Oxygen and Nutrient Report, July 2009, The Louis Berger Group, Inc.

